

# HISTORIC AMERICAN ENGINEERING RECORD

## Index to Photographs

Upper Mississippi River Nine-foot Channel Project,  
Lock and Dam No. 26R  
Alton vicinity, Illinois  
Madison County, Illinois  
St. Charles County, Missouri

HAER No. IL-32

NOTE: Photographs were taken by John P. Herr, photographer, John Herr Photography, October 1988

- IL-32-1      AERIAL VIEW OF LOCK CONSTRUCTION, LOOKING NORTH  
Photocopy of photograph no. 1458-35, May 6, 1988. Original slide on file at Mississippi River Lock and Dam No. 26R, Alton, Illinois
- IL-32-2      OVERALL VIEW OF DAM, LOOKING NORTH (UPSTREAM)
- IL-32-3      OVERALL VIEW OF DAM, LOOKING NORTHWEST (UPSTREAM) FROM  
DOWNSTREAM END OF LOCK OF COFFERDAM
- IL-32-4      DETAIL VIEW OF TAINTER GATE PIER AND TAINTER GATE NO. 7 AND NON-  
SUBMERSIBLE TAINTER GATES, LOOKING WEST (UPSTREAM)
- IL-32-5      DETAIL VIEW OF TAINTER GATE PIER AND NON-SUBMERSIBLE TAINTER  
GATE, LOOKING EAST (DOWNSTREAM)
- IL-32-6      DETAIL VIEW OF TAINTER GATE PIER AND NON-SUBMERSIBLE TAINTER  
GATE, SHOWING MAIN LOCK IN BACKGROUND, LOOKING NORTH (UPSTREAM)
- IL-32-7      DETAIL VIEW OF TAINTER GATE PIER AND NON-SUBMERSIBLE TAINTER  
GATES DURING ERECTION, SHOWING LEFT GATE IN OPEN POSITION AND  
RIGHT GATE IN CLOSED POSITION, LOOKING NORTH (UPSTREAM). NOTE  
TEMPORARY SERVICE BRIDGE.
- IL-32-8      DETAIL VIEW OF TAINTER GATE PIER AND NON-SUBMERSIBLE TAINTER  
GATE, LOOKING NORTH (UPSTREAM)
- IL-32-9      DETAIL VIEW OF NON-SUBMERSIBLE TAINTER GATE, LOOKING NORTHEAST  
(UPSTREAM)
- IL-32-10     DETAIL VIEW OF TAINTER GATE ARMATURE, LOOKING NORTH
- IL-32-11     DETAIL VIEW OF NON-SUBMERSIBLE TAINTER GATE, SHOWING CABLE  
ASSEMBLY ATTACHMENT, LOOKING EAST (DOWNSTREAM)
- IL-32-12     DETAIL VIEW OF TAINTER GATE CABLE ASSEMBLY, LOOKING SOUTH  
(DOWNSTREAM)

Upper Mississippi River Nine-Foot Channel Project,  
Lock and Dam No. 26R  
HAER No. IL-32  
Index to Photographs  
(Page 2)

- IL-32-13      DETAIL VIEW, OF TAINTER GATE PIER, SHOWING RECESSES FOR EMERGENCY BULKHEADS AND DOGGING DEVICES, LOOKING SOUTHEAST (DOWN FACE). UPSTREAM FACE OF TAINTER GATE IS VISIBLE IN UPPER RIGHT CORNER
- IL-32-14      DETAIL VIEW OF SERVICE BRIDGE, SHOWING TRAVELLING CRANE AND TAINTER GATE PIER WITH RECESSES FOR EMERGENCY BULKHEADS AND BULKHEAD DOGGING DEVICES, LOOKING NORTHEAST
- IL-32-15      DETAIL VIEW OF TAINTER GATE PIER HOUSING, LOOKING EAST
- IL-32-16      DETAIL VIEW OF TAINTER GATE OPERATING MACHINERY, LOOKING SOUTH
- IL-32-17      DETAIL VIEW OF MAIN LOCK AND MAIN LOCK COFFERDAM, LOOKING SOUTHEAST (DOWNSTREAM)
- IL-32-18      OVERALL VIEW OF MAIN LOCK, LOOKING SOUTHEAST (DOWNSTREAM)
- IL-32-19      OVERALL VIEW OF MAIN LOCK INTERIOR, LOOKING NORTHWEST (UPSTREAM). NOTE MITER GATES IN PROCESS OF ERECTION
- IL-32-20      DETAIL VIEW OF MAIN LOCK COFFERDAM, SHOWING SHEET PILE CELLS AND INTERIOR BERM, LOOKING NORTH (UPSTREAM)
- IL-32-21      DETAIL VIEW OF MAIN LOCK COFFERDAM AND UPSTREAM FIN, SHOWING UPPER GUIDE WALL AND UPPER END OF MAIN LOCK, LOOKING NORTH (UPSTREAM)
- IL-32-22      DETAIL VIEW OF MAIN LOCK COFFERDAM, SHOWING SHEET PILE CELLS, WELLPOINTS, AND INTERIOR BERM, LOOKING NORTHEAST
- IL-32-23      DETAIL VIEW OF A MAIN LOCK COFFERDAM PUMP STATION, LOOKING NORTH
- IL-32-24      DETAIL VIEW OF SHEET PILE CELL FOR COFFERDAM WITH TEMPLATE IN PLACE, LOOKING WEST
- IL-32-25      DETAIL VIEW OF CONCRETE MONOLITH CONSTRUCTION AT UPPER END OF MAIN LOCK AND DAM PIERS, LOOKING SOUTHEAST (DOWNSTREAM). NOTE GANTRY CRANES
- IL-32-26      DETAIL VIEW OF CONCRETE MONOLITH CONSTRUCTION AT UPPER END OF MAIN LOCK AND DAM PIERS, LOOKING SOUTHEAST (DOWNSTREAM)
- IL-32-27      DETAIL VIEW OF CONCRETE MONOLITH CONSTRUCTION AT DOWNSTREAM END OF WEST MAIN LOCK WALL, LOOKING SOUTHEAST

Upper Mississippi River Nine-Foot Channel Project,  
Lock and Dam No. 26R  
HAER No. IL-32  
Index to Photographs  
(Page 3)

- IL-32-28      DETAIL VIEW OF CONCRETE MIXING PLANT, LOOKING NORTH
- IL-32-29      DETAIL VIEW OF ROCK AND SAND LOADER, LOOKING NORTHEAST
- IL-32-30      DETAIL VIEW OF CONCRETE CHILLER PLANT, LOOKING NORTHEAST
- IL-32-31      OVERALL VIEW OF ESPLANADE AREA, LOOKING NORTHEAST

The following are photocopies of photographs, courtesy of U.S. Engineer Office, St. Louis, Missouri. Original slides are on file at Mississippi River Lock and Dam No. 26R, Alton, Illinois.

- IL-32-32      CELL #45 UNDER CONSTRUCTION. July 30, 1980
- IL-32-33      AERIAL VIEW OF CONSTRUCTION WORK WITHIN COFFERDAM NO. 1, LOOKING EAST. November 1982
- IL-32-34      PREPARATION FOR CONCRETE PLACEMENT. November 29, 1982
- IL-32-35      FOUR TAINTER GATES BEING INSTALLED. CONCRETE PLACEMENT OVER 99% COMPLETE. NOTE SECOND STAGE COFFERDAM CELL BEING INSTALLED IN THE DRY. April 6, 1984
- IL-32-36      VIEW OF DAM CONSTRUCTION, LOOKING NORTHEAST  
Photograph No. 1258-5. July 17, 1984
- IL-32-37      AERIAL VIEW OF DAM CONSTRUCTION. February 1985
- IL-32-38      AERIAL VIEW OF LOCK CONSTRUCTION  
Photograph No. 1458-11. May 6, 1988

The following are photocopies of original construction drawings, ca. 1980, courtesy of the U.S. Army Corps of Engineers, St. Louis, Missouri. Original drawings are on file at the district office.

- IL-32-39      LOCK AND DAM NO. 26 (REPLACEMENT). LOCK -- LOCK GATES -- MITER GATE -- GENERAL ARRANGEMENT AND SECTION. M-L 26(R) 21/1
- IL-32-40      LOCK AND DAM NO. 26 (REPLACEMENT). LOCK -- LOCK GATES -- MITER GATE, D.S. & U.S. ELEVATION, SECTIONS. M-L 26(R) 21/2
- IL-32-41      LOCK AND DAM NO. 26 (REPLACEMENT). LOCK -- LOCK GATES -- LIFT GATE, GATE LEAVES -- GENERAL ASSEMBLY. M-L 26(R) 21/28
- IL-32-42      LOCK AND DAM NO. 26 (REPLACEMENT). LOCK -- LOCK GATES -- LIFT GATE, DOWNSTREAM LEAF, D.S. ELEVATION & GIRDERS. M-L 26(R) 21/29

Upper Mississippi River Nine-Foot Channel Project,  
Lock and Dam No. 26R  
HAER No. IL-32  
Index to Photographs  
(Page 4)

- IL-32-43 LOCK AND DAM NO. 26 (REPLACEMENT). LOCK -- LOCK CULVERT VALVE -- GENERAL ARRANGEMENT. M-L 26(R) 22/1
- IL-32-44 LOCK AND DAM NO. 26 (REPLACEMENT). LOCK -- LOCK GUIDEWALLS -- DOWNSTREAM GUIDEWALL, PARTIAL ISOMETRIC VIEW. M-L 26(R) 26/40
- IL-32-45 LOCK AND DAM NO. 26 (REPLACEMENT). LOCK -- LIFT GATE MACHINERY - GENERAL ARRANGEMENT AT EL. 414.5. M-L 26(R) 30/2
- IL-32-46 LOCK AND DAM NO. 26 (REPLACEMENT). LOCK -- LIFT GATE MACHINERY - GENERAL ARRANGEMENT AT EL. 395.0. M-L 26(R) 30/3
- IL-32-47 LOCK AND DAM NO. 26 (REPLACEMENT). LOCK -- TAINTER GATE GENERAL ARRANGEMENT. M-L 26(R) 45/51
- IL-32-48 LOCK -- TAINTER GATE -- SIDE FRAME COVER DETAILS. M-L 26(R) 45/58
- IL-32-49 LOCK AND DAM NO. 26 (REPLACEMENT). FIRST STAGE DAM -- DAM CONCRETE -- TYPICAL PIER ISOMETRIC. M-L 26(R) 40/1
- IL-32-50 LOCK AND DAM NO. 26 (REPLACEMENT). FIRST STAGE DAM -- DAM CONCRETE -- GENERAL ARRANGEMENT -- SECTION AND ELEVATIONS. M-L 26(R) 40/3
- IL-32-51 LOCK AND DAM NO. 26 (REPLACEMENT). FIRST STAGE DAM -- TAINTER GATE -- GENERAL ARRANGEMENT. M-L 26(R) 45/1
- IL-32-52 LOCK AND DAM NO. 26 (REPLACEMENT). FIRST STAGE DAM -- TAINTER GATE HOIST-ASSEMBLY -- PLANS AND ELEVATIONS. M-L 26(R) 46/2
- IL-32-53 LOCK AND DAM NO. 26 (REPLACEMENT). AUXILIARY LOCK AND REMAINDER OF DAM CONTROL HOUSE -- ELEVATIONS. M-L 26 (R) 92/2
- IL-32-54 LOCK AND DAM NO. 26 (REPLACEMENT). AUXILIARY LOCK AND REMAINDER OF DAM CONTROL HOUSE -- BUILDING SECTION. M-L 26(R) 92/3
- IL-32-55 LOCK AND DAM NO. 26 (REPLACEMENT). AUXILIARY LOCK AND REMAINDER OF DAM CONTROL HOUSE -- BUILDING SECTION. M-L 26(R) 92/3
- IL-32-56 LOCK AND DAM NO. 26 (REPLACEMENT). AUXILIARY LOCK AND REMAINDER OF DAM -- CONCRETE MONOLITH PLAN AND WALL ELEVATIONS (WITH LOCK APPURTENANCES). Drawing V-601
- IL-32-57 LOCK AND DAM NO. 26 (REPLACEMENT). AUXILIARY LOCK AND REMAINDER OF DAM -- FILLING AND EMPTYING SYSTEM -- PLAN AND SECTIONS. Drawing V-602

Upper Mississippi River Nine-Foot Channel Project,  
Lock and Dam No. 26R  
HAER No. IL-32  
Index to Photographs  
(Page 5)

IL-32-58 LOCK AND DAM NO. 26 (REPLACEMENT). AUXILIARY LOCK AND REMAINDER  
OF DAM -- CULVERT VALVE MACHINERY -- GENERAL ARRANGEMENT.  
Drawing VI-201

IL-32-59 LOCK AND DAM NO. 26 (REPLACEMENT). LOCK CONTROL BUILDING,  
CONTROL HOUSE, WALL SECTION & PERSPECTIVE. Drawing X-3